

CARE AND MAINTENANCE INSTRUCTIONS OF PREFINISHED STAKI OAK FLOOR

FEATURES	COLOURS OF STAKI OAK FLOORING	
		Clear, Extra white, Blanc white, Light white, Silver grey, Walnut, Ebony, Rosewood, Basalt, Amber, Castle brown, Antique white, White intense, Oak, Dark Oak, Raw
TOP COAT	LED oil	
FINISHING	After floor installation producer recommends to put extra coat of "Premium Hardwax oil".	
CARE AND FREQUENCY	First wet floor cleaning just after three weeks from oiling. Weekly cleaning using "Saicos Wash Care"*. Periodic cleaning with "Saicos Wax Care"*.	
MAINTENANCE	For floor maintenance and refreshing use "Premium Hardwax oil"*. For average wear - 1-2 times per year, for intensive wear – 3-4 times per year.	
SURFACE RENOVATION	After restauration floor color wouldn't be identical to factory finish.	After floor sanding identical floor color is not renewed.
OPERATING CONDITIONS	For residential and commercial use.	
VARIATIONS OF FLOORS AFTER FINISHING	<p>Might occur variations in width and height till 1.55% of board's width and thickness.</p> <p>Different wood hardness and surface structure can influence the ability to absorb oil into wooden floor's surfaces, e.i. possible color differences;</p>	

FEATURES	COLOURS OF STAKI OAK FLOORING	
		Tobacco, Autumn, Rime, Truffle, Vinted
TOP COAT	LED Oil	
FINISHING	After floor installation producer recommends to put extra coat of "Premium Hardwax oil".	
CARE AND FREQUENCY	First wet floor cleaning just after three weeks from oiling. Weekly cleaning using "Saicos Wash Care"*. Periodic cleaning with "Saicos Wax Care"*.	
MAINTENANCE	For floor maintenance and refreshing use "Premium Hardwax oil"*. For average wear - 1-2 times per year, for intensive wear – 3-4 times per year.	
SURFACE RENOVATION	After floor sanding identical floor color is not renewed.	
OPERATING CONDITIONS	For residential and commercial use.	
VARIATIONS OF FLOORS AFTER FINISHING	<p>Might occur variations in width and height till 1.7% of board's width and thickness.</p> <p>Different wood hardness and surface structure can influence the ability to absorb oil into wooden floor's surfaces, e.i. possible color differences;</p> <p>After processing in an alkaline environment, may be differences in color, even in the same board, because of the different content of tannins in the wood. Note, that right away after production floor color is more intensive.</p>	

FEATURES	COLOURS OF STAKI OAK FLOORING	
	Invisible	Naturio, Brazil, Bunyoro
TOP COAT	Hardwax oil	
FINISHING	After floor installation producer recommends to put extra coat of "Osmo Maintenance oil".	After installation STAKI floor has to be oiled with "Floorservice Maintenance Oil"*.
CARE AND FREQUENCY	First wet floor cleaning just after three weeks from oiling. Weekly cleaning using "Osmo Wash & Care"*. Periodic cleaning with "Osmo Liquid Wax Cleaner"*.	First wet floor cleaning just after two weeks from oiling. Daily dry cleaning with "Floorservice Dry cleaning Set"*. Periodic cleaning with "Floorservice Parquet cleaner"*.
MAINTENANCE	For floor maintenance and refreshing use "Premium Hardwax oil"*. For average wear - 1-2 times per year, for intensive wear – 3-4 times per year with*.	For floor maintenance and refreshing use "Floorservice Color Hardwax-oil Classic". For average wear - 1-2 times per year, for intensive wear – 3-4 times per year with*.
SURFACE RENOVATION	After restauration floor color wouldn't be identical to factory finish.	
OPERATING CONDITIONS	For residential and commercial use.	
VARIATIONS OF FLOORS AFTER FINISHING	Might occur variations in width and height till 1.55% of board's width and thickness. Different wood hardness and surface structure can influence the ability to absorb oil into wooden floor's surfaces, e.i. possible color differences;	

FEATURES	COLOURS OF STAKI OAK FLOORING	
	Cuba	Clear lacquer, Ivory
TOP COAT	UV lacquer	
FINISHING	Finished product	
CARE AND FREQUENCY	Daily dry cleaning with "Floorservice Dry cleaning Set"*. Periodic cleaning with "Floorservice Parquet cleaner"*.	
MAINTENANCE	Depends from floor wearing.	
SURFACE RENOVATION	After floor sanding identical floor color is not renewed.	
OPERATING CONDITIONS	For residential and commercial use.	
VARIATIONS OF FLOORS AFTER FINISHING	Might occur variations in width and height till 1.7% of board's width and thickness. After processing in an alkaline environment, may be differences in color, even in the same board, because of the different content of tannins in the wood. Note, that right away after production floor color is more intensive.	Might occur variations in width and height till 1.55% of board's width and thickness.
	Different wood hardness and surface structure can influence the ability to absorb oil into wooden floor's surfaces, e.i. possible color differences;	

Solid oak floor board's dimensions are given at a reference moisture content of 9%, and engineered parquet and TOP-LAG flooring at 7%. It shall be assumed that the thickness and width of floorboard increase by 0.25% for every 1% of moisture content above the reference moisture content, and decrease by 0.25% for every 1% of moisture content below the reference moisture content. For more precise calculation, the veneer should be conditioned and all dimensions should be evaluated through laboratory tests.

* According to oils manufacturer's instructions and requirements.

Information copied and distributed without company ["Plankmara"](#) Ltd permission is strictly prohibited. STAKI reserves the right to correct and update the provided information. Last update 01 06 2023.